

SERVICE INSTRUCTIONS
WELDED EXPOSURE RACK



applicable models:	Standard Welded Exposure Rack
applicable serial numbers:	N/A
applicable kit numbers:	FL-3049-K

Approvals		
written by:	reviewed by:	approved by:


Safety Reminder

These instructions do not intend to address all of the safety problems, if any, associated with their use. It is the responsibility of the user of these instructions to establish appropriate safety and health practices and to determine the applicability of regulatory limitations prior to use.


Summary

These instructions are a step by step graphic diagram of how to assemble a Q-Lab standard welded rack.

Kit Contains:




A (1)












B (1)



C (5)




D (2)




Tools Needed:




Instructions:



Step 1




Step 2




Step 3




Step 4




Step 5
Set flap distance



Step 6



Step 7
Install legs



Step 8



Step 9
Both sides